



KMLB

LIVE'S BROADCASTING STATION

STUDIO 512-16 SOUTH GRAND STREET

Monroe, Louisiana.

March 5th., 1932.

Answering Yours
February 26th.

Mr. J. W. Brauner,
Williamsville, N.Y.

Dear Mr. Brauner:-

I am at a loss to explain why you are unable to pick up KMLB. I get consistant reports from every state east of the Rockies every time we put on a DX program. On the program you were unable to pick up the other night I received eighteen reports from Canada.

Evidently you are in a deadspot for us. It seems that Burton Proctor is also in your fix for he nevers seems to be able to pick us up.

I am enclosing a report from J. W. DeRosa on our program of the 26th. You can judge for yourself from his report whether or not the fault lies with us.

We pride ourselves on having the best 100 watt station in the south and it hurts when someone blames us because they cannot receive our station. I assure you that I will cooperate with you to the fullest in your attempts to log us.

Our transmitter is modern in every respect and has been checking consistantly under 50 cycles. An oscillagraph picture of our wave shows that we are modulating 100% with less that 1% audio harmonics.



Very sincerely yours,

73 *J. B. Limerick*