



Box 147 ■ Bozeman, Montana 59715 ■ (406) 586-5466

May 17, 1979

Mr. Bill Nittler  
603 West First  
McCook, NE 69001

Dear Mr. Nittler:

This confirms your reception report of November 8, 1976, at 2:05 AM MST. KBOZ was non-directional during the time of your report for frequency check purposes. KBOZ resumed directional mode after the test, thus explaining the loss of signal at 2:09 AM.

Thank you for your report.

A handwritten signature in cursive script that reads 'Stephen H. Blodgett'.

Stephen H. Blodgett  
Chief Engineer, KBOZ