

2627 EAST 4th STREET

316-663-2115



August 28, 1977

Bobby R. Propst
Chief Engineer
KSKU FM Radio
Hutchinson, Kansas 67501

Bill Nittler
603 West 1st
McCook, Nebraska 69001

Dear Mr. Nittler,

I found your letter in my box this morning. Evidently our General Manager had put the letter in his files and forgot about it until he was cleaning them out yesterday afternoon.

I went over our program log and found your logging of our program to be mostly accurate. There were two discrepancies. Leonardo's Steakhouse was actually Leonida's Steakhouse, and FM-93 was FM-102. Either discrepancy could be accounted for by obvious instability of our signal.

Our radiated power is 100 KW at 102.1 Mhz. Our transmitter power is 18.5 KW.

I enjoyed your letter very much. I have just recently learned of DXing and find the subject extremely interesting.

I am enclosing one of our "Chrome-Plated" bumper stickers.

Thanks for the letter,

Bobby R. Propst
Chief Engineer

BRP