

WAPC

TEL. PARK 7-1570

P. O. BOX 666
RIVERHEAD, N. Y.

Mr Stanwood R. Morss
Rfd 3
Bradford - Massachusetts

Aug 23rd 1963

Dear Mr Morss:

Thank you for the report of reception.
It is essentially correct. Our first day of operation
was the 8th, & we have a two-tower directional
pattern to the southeast.

Your receiver is a good one, but a direction-
finder would help where many stations operate on
the same frequency, especially if you do a good
deal of listening.

73-

Robert Perkins Thayer
Supervising Engineer